
Page 1 of 3

59215838 A



(11) Publication number:

59215838 A

Generated Document,

PATENT ABSTRACTS OF JAPAN

(21) Application number: 58092754

24.05.83

(22) Application date:

(51) Intl. Cl.: B29F 1/00

(30) Priority:

05.12.84 (43) Date of application publication:

(84) Designated contracting states:

(71) Applicant: MITSUBISHI ELECTRIC CORP **NISHIYAMA HIDEO** (72) Inventor: SHIGESATO HIDEO

(74) Representative:

(54) MOLDING APPARATUS

(57) Abstract:

ultraviolet rays into a cavity core with ray source provided separate from the an optical fiber from an ultra violet enabling the prevention of possible PURPOSE: To improve the safety cavity core to irradiate a molding ozone and others by introducing material

injected into a die 1 from an injection CONSTITUTION: An ultraviolet ray hardening molding material 14 is

https://www.delphion.com/cgi-bin/viewpat.cmd/JP59215838A2

PAGE 60/105 * RCVD AT 9/21/2004 8:07:23 PM [Eastern Daylight Time] * SVR:USPTO-EFXRF-1/1 * DNIS:8729306 * CSID:9497372900 * DURATION (mm-ss):25-02

Page 2 of 3


S9215838 A

molding machine 13 to fill the space between a cavity core 5. Then, ultraviolet rays irradiate the cavity 4 and the cavity core 5 separately via an optical fiber 6 from a ultraviolet rays irradiation source 7. The ultraviolet rays are irradiated on the molding material filled between the cavity and cavity core being reflected on reflection layers 8 and 9 to solidify the molding material quickly. The molding thus solidified is released from the die by sticking out an ejector pin 10 from the cavity core 5 at the opening of the die.

COPYRIGHT: (C)1984, IPO& Japio

Page 3 of 3

https://www.delphion.com/cgi-bin/viewpat.cmd/JP59215838A2



This Page is Inserted by IFW Indexing and Scanning Operations and is not part of the Official Record

BEST AVAILABLE IMAGES

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images include but are not limited to the items checked:

BLACK BORDERS

IMAGE CUT OFF AT TOP, BOTTOM OR SIDES

FADED TEXT OR DRAWING

BLURRED OR ILLEGIBLE TEXT OR DRAWING

SKEWED/SLANTED IMAGES

COLOR OR BLACK AND WHITE PHOTOGRAPHS

GRAY SCALE DOCUMENTS

LINES OR MARKS ON ORIGINAL DOCUMENT

REFERENCE(S) OR EXHIBIT(S) SUBMITTED ARE POOR QUALITY

IMAGES ARE BEST AVAILABLE COPY.

☐ OTHER:

As rescanning these documents will not correct the image problems checked, please do not report these problems to the IFW Image Problem Mailbox.